


# *Rock Island District in the 20th Century*



**Aug. 13  
1934**

Concrete being placed into forms for the lower guidewall. L&D #15.



**Nov. 11  
1936**

Power control and lighting Dam #18. Foundation of gasoline stand-by unit.



**Aug. 31  
1954**

L&D #17, electrical construction crew raising lamp into place.

Portion of T-piling being removed because it was hit by towboat. L&D #19



**May 9  
1939**



**July 17  
1957**

Coralville Reservoir, Stage III construction of Dam Spillway.